

Monthly Status Report
Robert Stobie Prime Focus Imaging Spectrograph
June 2007

K. Nordsieck

This RSS monthly report summarizes the RSS status as of July 9, 2007.

Optics and Testing

- Progress toward a repair of the UV loss problem:
 - A successful fluid expansion bladder composed of polyethylene LDPE has been constructed.
 - Draining and refilling of the multipllets is underway, starting with the collimator doublet. For the first drain/ refill, the procedure is as follows: After draining the cell of the old (LL5610) fluid, flush it a couple times, recycling the alcohol. Then change the alcohol and flush it a couple more times. Measure the transmission in the UV of the used alcohol to see how much of the old fluid it contains, and then flush again depending on the results. This should give us a quantitative measure of the UV attenuation that we could expect when the cell is refilled with the new fluid (an upper limit, anyway). Once it's sufficiently flushed, put the cell in a vacuum to (gently) boil off the residual alcohol. Then refill with LL3421 fluid at atmospheric pressure.
- The failed field flattener coating has been polished off at Janos, the surface recoated at Spectrum Thin Films, and the element shipped to Pilot Group for a final transmission measurement. An improved water-resistant overcoat was applied to the new coating. Transmission and reflectivity measurements of a sample with our AR coating plus the overcoat verified that the overcoat does not degrade the AR performance or transmission. A fused silica witness with our coating/ overcoat is being supplied with the part for our testing.

Mechanical

- Etalon mechanism. A modification to the etalon seating fixture has been devised to improve the etalon flexure during an observation. Machining is complete.
- The guidance probe is being modified to eliminate interference which prevented its use in some parts of the field of view. The parts on the probe that interfered (and included strain reliefs for the fibers) have been redesigned, manufactured and test fitted.

Control

- Electronics box fixes: New, more robust electronics box brackets have been designed for the four electronics boxes. A design review has been held, with some suggested changes.


- Detector work continues:
 - Anomalous CCD full well: A change to the current four gain/ speed choices is under investigation, in which the BRIGHT/ FAST mode uses low sensitivity, and FAINT/FAST uses high sensitivity but a lower gain. We are evaluating the noise and gain before proceeding with a modification.
 - An improved temperature control method is being implemented. Breadboard testing is complete. We have designed a permanent solution, and have components on order, delivery date ~19th July. The solution will allow for remote control of servo control variables such as temperature set-point etc.
 - Earth-loop /chevron pattern tests: Tests done in the lab indicate that at gains of $1e/ADU$ in both FAST & SLOW readout speeds, the chevron pattern is undetectable by eye in the displayed image, even when applying a very aggressive lookup table. The pattern becomes visible at gains of around $0.3e/ADU$
- Coding of the high level PCON control software is in progress. The execution engine has been optimized, and the TCP connection code has been made much simpler and more reliable. However, implementation of the TCS interaction is being postponed until after Janus Brink returns from leave.

Management

- The RSS schedule has been updated, and is attached to this report. The ship date of the optics from California is now 20 July, with a possible one-week slip. This shipment will include the field flattener.
- The 2007 Quarter 1 Quarterly Management Report was finished.

Activities for next month

- Analysis
 - Work on analysis of polarimetric commissioning data.
- Optics
 - Complete draining/ refilling of multipllets; remeasure transmission.
- Mechanical
 - Finish testing the reworked slitmask mechanism.
 - Repair old grating rotation stage (PI). Test flexure of new stage.
 - Design improved instrument installation and removal fixtures.
 - Review optics and instrument installation/ removal procedures.
 - Work on baffling improvements for the moving baffle and filter insertion seal.
 - Complete reworked guide probe assembly plus some other improvements on the cabling and routing.
- Control
 - Continue coding of PCON high-level control software, starting with engineering controls, and then proceeding to PDET interaction.
 - Integrate CCD improved temperature control, in parallel with the reinstallation of the field flattener lens in the cryostat if necessary.
- Detector
 - Finish testing of detector readout mode modifications to improve full well.
 - Complete temperature control modifications.
- Management
 - Ship optics and alignment equipment to South Africa.
 - Start Quarter 2, 2007 Quarterly Management Report.



ID	Task Name	Start	Finish	% Complete
63	Installation/Removal Improvements	Mon 18/07	Fri 19/07	66%
64	Wire RSS installation/removal procedure	Mon 18/07	Tue 20/07	100%
65	Ship Invar Tubing	Mon 18/07	Fri 19/07	100%
66	Reroute payload & RSS cabling	Mon 22/07	Fri 26/07	0%
67	Design lifting arrangement for RSS	Mon 22/07	Fri 26/07	0%
68	Procedures	Mon 18/07	Wed 18/07	51%
69	Magazine station alignment procedure	Mon 18/07	Wed 18/07	41%
70	Sirnaak mechanism alignment procedure	Tue 19/07	Mon 24/07	0%
71	Optics Changeout Procedure - Elson	Mon 18/07	Tue 20/07	100%
72	Optics Changeout Procedure - Detector	Mon 22/07	Tue 23/07	26%
73	Optics Changeout Procedure - Sirnaak	Mon 22/07	Tue 23/07	38%
74	Optics Changeout Procedure - Filter magazine	Mon 18/07	Tue 20/07	100%
75	Optics Changeout Procedure - Grating magazine	Mon 18/07	Tue 20/07	100%
76	Optics Changeout Procedure - Beam splitter	Mon 22/07	Fri 26/07	0%
77	Software	Wed 12/07	Tue 23/07	87%
78	SRO Review	Wed 12/07	Wed 12/07	100%
79	Wire Software Design Document	Wed 12/07	Tue 22/07	100%
80	Implement	Wed 22/07	Tue 23/07	85%
81	Optics Repair	Wed 12/07	Tue 22/07	80%
82	Ship Optics -> Plot	Wed 12/07	Tue 22/07	100%
83	Disassemble Cam, Coil Multiplex	Wed 13/07	Tue 20/07	100%
84	Transmission of Multiplex	Wed 13/07	Tue 22/07	100%
85	Fatiguer Repair	Wed 22/07	Fri 24/07	79%
86	Evaluation/ Clean Attempt	Wed 22/07	Tue 23/07	100%
87	Polish of coating	Wed 22/07	Fri 24/07	100%
88	Recoat	Mon 25/07	Fri 26/07	100%
89	Transmission	Mon 25/07	Fri 26/07	0%
90	Ship Optics -> SA	Mon 25/07	Fri 26/07	0%
91	Replace window, pumpdown	Mon 25/07	Fri 26/07	0%
92	UV Throughput Repair	Wed 22/07	Fri 24/07	100%
93	Measure Fluid Samples	Wed 22/07	Tue 23/07	100%
94	Investigate Gassy Loss	Wed 22/07	Fri 24/07	100%
95	Fluid Bladder Compatibility Tests	Mon 22/07	Fri 26/07	100%
96	Camera Triplet repair	Mon 22/07	Fri 26/07	83%
97	Disassemble/Inspect	Mon 22/07	Fri 26/07	100%
98	Repair	Mon 22/07	Fri 26/07	76%
99	Design/Rebuild Bladders	Mon 22/07	Fri 26/07	96%
100	Drain/Refill Fluid	Mon 22/07	Fri 26/07	10%
101	Transmission of Multiplex	Mon 22/07	Fri 26/07	0%
102	Reassemble/Align Cam, Coil	Mon 22/07	Fri 26/07	0%
103	Ship Optics -> SA	Mon 22/07	Fri 26/07	0%
104	Beam splitter Repair	Mon 22/07	Tue 23/07	25%
105	Transmission	Mon 22/07	Fri 26/07	100%
106	Replace Fluid Bladder	Mon 22/07	Thu 25/07	0%
107	Ship -> SA	Fri 26/07	Tue 27/07	0%
108	Reintegration	Mon 29/07	Wed 31/07	0%
109	Rentail optics	Mon 29/07	Wed 31/07	0%
110	Align Optics	Thu 25/07	Wed 31/07	0%
111	Reintegrate mechanisms, balling	Thu 25/07	Wed 31/07	0%
112	Residuals Test	Thu 25/07	Wed 31/07	0%
113	Ready for UAT	Wed 29/07	Wed 31/07	0%